

MONUMENT RECORD
State of Indiana - County of Monroe

Township: 9 North

Range: 2 West

Corner ID: Rich W-07


Monument Description & Remarks: Found 1" o.d. crimped Iron Pipe at center of section. Iron pipe was 5" above ground, marked with multiple layers of surveyor's flagging.

References on file in the County Surveyor's Office: Survey by Kevin Potter, R.L.S. of Nice/Illman Subdivision.

RECOVERY TIE DRAWING

Field Book 98-02 Page No. 13

USGS Bloomington Quad



A - 1" crimped iron pipe

B - South 23 degrees East, 17.26' from iron pipe

MAG nail in 28" forked Black Oak

C - South 88 degrees West, 32.39' from iron pipe

MAG nail in 5" round post

D - North 09 degrees East, 8.02' from iron pipe

MAG nail in 9" Shagbark Hickory

- At Corner

Not To Scale

Compass Bearing Magnetic North

I, Kevin P. Enright, Monroe County Surveyor, hereby certify that this document was prepared under my direction in accordance with the provisions of Section 30-1-1 of the Indiana Code; and the above data is given under my hand and seal this 16th day of June, 1998.

Administered by: Surveyor Review Board